



2 **CEILING PLAN**  
A1 / 2 SCALE 1:100 METERS

**NOTES:**

<p><b>DEMOLITION &amp; REPLACEMENT</b></p> <ol style="list-style-type: none"> <li>1. DEMOLITION &amp; REPLACEMENT OF DETERIORATED WOODEN FLOORING</li> <li>2. REMOVAL &amp; REPLACEMENT OF CEILING MATERIALS</li> <li>3. DEMOLITION &amp; REPLACEMENT OF WALLING MATERIALS</li> <li>4. REMOVAL &amp; REPLACEMENT OF ROOFING MATERIALS</li> </ol> <p><b>DOORS &amp; WINDOWS(COMPLETION)</b></p> <ol style="list-style-type: none"> <li>1. INSTALLATION OF NEW WOODEN DOORS</li> <li>2. REFURBISH EXISTING DOORS &amp; JAMBS</li> <li>3. REHABILITATE WOODEN FRAME WINDOW CASING</li> <li>4. INSTALLATION OF NEW DOOR LOCKSET &amp; HARDWARE</li> <li>5. INSTALLATION OF NEW CASPIZ</li> </ol> <p><b>CARPENTRY &amp; WOODWORKS</b></p> <ol style="list-style-type: none"> <li>1. REPLACEMENT OF DAMAGED &amp; DETERIORATED WOODEN POST</li> <li>2. REPLACEMENT OF DAMAGED &amp; DETERIORATED FLOOR FRAMING</li> <li>3. REPLACEMENT OF DAMAGED &amp; DETERIORATED ROOF GIRDERS</li> <li>4. REHABILITATION OF WOODEN TRUSSES</li> <li>5. REPLACEMENT OF DAMAGED &amp; DETERIORATED 3/4" X 4" T&amp;G FLOORING</li> <li>6. REPLACEMENT OF DAMAGED &amp; DETERIORATED EXISTING WOODEN WALL</li> <li>7. REPAIR OF EXISTING INTERIOR/ EXTERIOR WOODEN WALL</li> <li>8. REPAIR OF INTERIOR WOODEN WALL</li> <li>9. REPLACEMENT OF DAMAGED &amp; DETERIORATED 3/4" X 4" T&amp;G CEILING</li> <li>10. NEW INSTALL. FIBER BOARD CEILING</li> </ol> <p><b>MOISTURE PROTECTION</b></p> <ol style="list-style-type: none"> <li>1. APPLICATION OF ANTI ANHY TREATMENT</li> <li>2. APPLICATION OF EPOXY PAINT</li> </ol> <p><b>ROOFING WORKS</b></p> <ol style="list-style-type: none"> <li>1. REMOVAL &amp; REPLACEMENT OF ROOFING</li> <li>2. INSTALLATION OF VALLEY GUTTER</li> </ol>	<p><b>FINISHING WORKS</b></p> <ol style="list-style-type: none"> <li>1. REPAIRING OF INTERIOR &amp; EXTERIOR WOODEN WALL WITH SEMI-GLOSS PAINT</li> <li>2. REPAIRING OF CEILING &amp; CORNER WITH FLAT PAINT</li> <li>3. PAINTING OF BASEBOARDS</li> <li>4. VARNISHING OF WOODEN DOORS</li> <li>5. REPAIRING OF WOODEN JAMBS &amp; LOUVERS WITH OIL</li> </ol> <p><b>TOILETS</b></p> <ol style="list-style-type: none"> <li>1. NEW TOILETS CONSTRUCTION(COMPLETION)</li> </ol> <p><b>FACADE(COMPLETION)</b></p> <ol style="list-style-type: none"> <li>1. TILING WORKS AT THE ENTRANCE</li> <li>2. REHABILITATION OF WOODEN FACADE AT FRONT PORTION</li> <li>3. REHABILITATION OF WOODEN STAIRS AT FRONT PORTION</li> </ol>
---	---

REPUBLIC OF THE PHILIPPINES  
 DEPARTMENT OF EDUCATION  
 PHYSICAL FACILITIES AND SCHOOLS ENGINEERING DIVISION  
 DIVISION OF MISAMIS ORIENTAL  
 A.VELEZ ST., CAGAYAN DE ORO CITY

**PREPARED BY:**  
 SANDY L. SIMO  
 CIVIL ENGINEER

**PROJ. NO.:**  
**PERIOD:**  
**DATE:**  
**PLACE:**  
**TWN. NO.:**

**DESIGNED BY:**  
 RUDY O. MAGDUGO  
 CHIEF, 9000

**PROJECT TITLE:**  
 PROPOSED REPAIR OF MODIFIED GABALDON BUILDING (4CL) IN HAWAWAN CENTRAL SCHOOL  
 MISAMIS ORIENTAL DIVISION

**APPROVED BY:**  
 CHERRY MAE L. LIMBACO, Ph.D., CESO V  
 SCHOOLS DIVISION SUPERINTENDENT

**SHEET CONTENT:**  
 CEILING PLAN  
 LIGHTING LAY-OUT  
 PROGRAM OF WORKS

**SHEET NO.:**  
 A1  
 01 / 01