




ROOF FRAMING PLAN

SCALE 1:50 H.




SECTION THRU " E-E "

DRAWN NOT TO SCALE



CEILING VENT DETAIL

SCALE 1:15 H.



SCHEDULE OF DOORS AND WINDOWS

SCALE 1:40 H.

<div><div><div><div><div><div></div><div>DepEd</div></div><div><div>Department of Education</div><div><div><div>Division Office - Misamis Oriental</div><div>A. Velasco Street, Cagayan de Oro City</div></div></div></div></div><div><div>PROJECT TITLE:</div><div>REPAIR / REHABILITATION OF ONE STOREY TWO (2) CLASSROOMS BAGONG LIPUNAN TYPE WITH ATTACHED CR</div></div></div></div></div>			<div><div>OFFICE OF THE SCHOOLS DIVISION SUPERINTENDENT</div><div>DEPED DIVISION OF MISAMIS ORIENTAL</div></div> <div><div>PREPARED BY:</div><div>ENGR. SANDY L. SIMO, CE</div><div>Division Engineer, III</div></div> <div><div>RECOMMENDING APPROVAL:</div><div>RUDY O. MAGDUGO</div><div>Chief, SGDO</div></div> <div><div>APPROVED:</div><div>CHERRY MAE L. LIMBAGO, Ph.D., CESO V</div><div>SCHOOLS DIVISION SUPERINTENDENT</div></div>			<div><div>SHEET CONTENTS :</div><div>ROOF FRAMING PLAN SECTION THRU " E-E " CEILING VENT DETAIL SCHEDULE OF DOORS AND WINDOWS</div></div> <div><div>SHEET NUMBER</div><div>02 of 02</div></div>
---	--	--	--	--	--	---