


<div><div><div><div><div></div><div>DEPARTMENT OF EDUCATION</div><div>DIVISION OF MISAMIS ORIENTAL</div><div>A. Velaz Street Cagayan de Oro City</div></div><div>PROJECT TITLE :</div><div>REPAIR / REHABILITATION OF ONE STOREY ONE (1) CLASSROOM DEPED TYPE WITH ATTACHED CR</div></div></div></div>			<div><div>OFFICE OF THE SCHOOLS DIVISION SUPERINTENDENT</div><div>DEPED DIVISION OF MISAMIS ORIENTAL</div></div>			<div><div>SHEET CONTENTS :</div><div>BLACK BOARD DETAIL DOOR AND WINDOWS AIR VENT SECTION AT B-B</div></div>		<div><div>SHEET NUMBER</div><div>02 of 03</div></div>	
<div><div>SCHOOL :</div><div>LOAJONES ALIBUDID ELEMENTARY SCHOOL</div><div>DIVISION :</div><div>MISAMIS ORIENTAL</div></div>			<div><div>PREPARED BY:</div><div>ENGR. SANDY L. SIMO , CE</div></div>		<div><div>RECOMMENDING APPROVAL:</div><div>RUDY O. MAGDUGO</div></div>		<div><div>APPROVED:</div><div>CHERRY MAE L. LIMBAGO, Ph.D. , CESO V</div></div>		
<div><div>ADDRESS :</div><div>ALIBUDID, MISAMIS ORIENTAL</div></div>			<div><div>Division Engineer III</div></div>		<div><div>SCHOOLS DIVISION SUPERINTENDENT</div></div>				