



| NOTES: | |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| DEMOLITION & REPLACEMENT 1. DEMOLITION & REPLACEMENT OF DOORS 2. DEMOLITION & REPLACEMENT OF CEILING 3. DEMOLITION & REPLACEMENT OF WALLING 4. DEMOLITION & REPLACEMENT OF ROOFING | FINISHING WORKS 1. REPAIRING OF INTERIOR & EXTERIOR WOODEN WALL WITH HSB-GLOSS PAINT 2. REPAIRING OF CEILING & CORNICE WITH FLAT PAINT 3. PAINTING OF BARRIERS 4. VARNISHING OF WOODEN DOORS 5. REPAIRING OF WOODEN JAMBS & LOUVERS WITH GDE |
| DOORS & WINDOWS/COMPLETION 1. INSTALLATION OF NEW WOODEN DOORS 2. REPAIRING EXISTING DOORS & JAMBS 3. REPAIR/INSTALL WOODEN FRAME WINDOW CASING 4. INSTALLATION OF NEW DOOR LOCKSET & HANDLE 5. INSTALLATION OF NEW CAPIZ WINDOWS | TOILETS 1. NEW TOILETS CONSTRUCTION/COMPLETION |
| CARPENTRY & WOODWORKS 1. REPLACEMENT OF DAMAGED & DETERIORATED WOODEN POST 2. REPLACEMENT OF DAMAGED & DETERIORATED FLOOR PLANKING 3. REPLACEMENT OF DAMAGED & DETERIORATED ROOF GIRDERS 4. REHABILITATION OF WOODEN TRUSSES 5. REPLACEMENT OF DAMAGED & DETERIORATED 3" x 4" + 1" THICK FLOORING 6. REPLACEMENT OF DAMAGED & DETERIORATED EXISTING WOODEN WALL 7. REPAIR OF EXISTING INTERIOR / EXTERIOR WOODEN WALL 8. REPAIR OF INTERIOR WOODEN WALL 9. REPLACEMENT OF DAMAGED & DETERIORATED 3/4" x 4" + 1" THICK CEILING 10. NEW INTERNAL BROWN BOARD CEILING | FAÇADE/COMPLETION 1. TILING WORKS AT THE ENTRANCE 2. REHABILITATION OF WOODEN FACADE AT FRONT PORTION 3. REHABILITATION OF WOODEN STAIRS AT FRONT PORTION |
| MOISTURE PROTECTION 1. APPLICATION OF ANTI ANI TREATMENT 2. APPLICATION OF SPOKY PAINT | |
| ROOFING WORKS 1. REMOVAL & REPLACEMENT OF ROOFING 2. INSTALLATION OF VALLEY OUTLET. | |

| | | | | | | | | |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|-------------|---------------------------|---------------------------------|----------------------------------------------------------------------------------|--------------------------------------|--------------------------------|-----------|
| REPUBLIC OF THE PHILIPPINES DEPARTMENT OF EDUCATION PHYSICAL FACILITIES AND SCHOOLS ENGINEERING DIVISION DIVISION OF MISAMIS ORIENTAL A. VELAZ ST., CAGAYAN DE ORO CITY | PREPARED BY: | PROJ. NO. | BSAL | NOTED BY: | PROJECT TITLE: | APPROVED BY: | SHEET CONTENT: | SHEET NO. |
| | SANDY L. SIMO | PRJ. NO. | | RUDY O. MAGDUGO | PROPOSED REPAIR OF MODIFIED GALBARDON BUILDING (4CL) IN NAAWAN CENTRAL SCHOOL | CHERRY MAE L. LIMBACO, Ph.D., CESO V | FLOOR PLAN PROGRAM OF WORKS | A1 |
| | | DATE | | | | | | |
| | | PLACE | | | | | | |
| CIVIL ENGINEER | TRN NO. | CHIEF, GOOD | MISAMIS ORIENTAL DIVISION | SCHOOLS DIVISION SUPERINTENDENT | | 01 | 01 | |